



# RENOVATION



EXISTING OAK PLANK BEARING CONSTRUCTION WAS STRUCTURALLY AND STATICALLY IN POOR CONDITION. IT WAS RENEWED AND PROTECTED FROM FURTHER DETERIORATION.

